

# WATER BASE FLEXOGRAPHIC INK ADDITIVES



## **DEFOAMER 00AFW7038**

The flow of ink fall in the pump return , the hardness of water quality and the pump type, foaming problem may occur . in this case we advise to add up to %2 defoamer  $00AFT\ 7038$ 

## REDUCER 00FWB8529

To reduce the ink to proper viscosity and to improve the gloss and rub resistance and also to lower the colour density for high absorbent paper add %10 reducer 00FWB8529

#### RETARDER 00SLV8221

In hot season due to the warm weather the drying speed of ink increase and ink may pick the paper particles . adding 5-10% of retarder 00SLV8221 will overcome the problem and yields the best quality .

## 00SLV7318

Inks may dry in the anilox roller and so the print quality decreases washing anilox roller monthly is essential. 00SLV7318 clean the anilox roller throughly and refresh the roll.

#### 00SLV7032

Water is the best solvent to clean the printing machine but to clean the printing machine throughly specialy for charging colour 7032 is helpful and easily clean the machine

